

MAY 02 2007



MISSOURI DEPARTMENT OF AGRICULTURE
 DIVISION OF WEIGHTS AND MEASURES SCALE PROGRAM
 P.O. BOX 530, JEFFERSON CITY, MISSOURI 65102 (573) 751-5639
SCALE INSPECTION REPORT/FEE INVOICE

COUNTY GREENE	INSP. CODE 04	PAGE 01 OF 03
DATE 4-24-07		INVOICE NUMBER 203533

FROM NAME AND STREET ADDRESS 077-0095 PRICECUTTER #18 1901 E DIVISION SPRINGFIELD TELEPHONE NUMBER (417) 866-5502	BILLING ADDRESS IF DIFFERENT PRICECUTTER #18 1901 E DIVISION SPRINGFIELD, MO 65803 TELEPHONE NUMBER
---	--

	NAME	TYPE	SERIAL NUMBER	CAPACITY	ZERO AS FOUND	0 TO 1 LB	10 TEST LOAD	25 TEST LOAD	50% TEST LOAD	MAXIMUM TEST LOAD	ACTION CODE	FEE	
1.	DETECTO	HG	9502085	30			<i>Not Sealed</i>				N	5.00	
2.	DETECTO	HG	9502086	30			"	"			N	5.00	
3.	DETECTO	HG	9502087	30			"	"			N	5.00	
4.	DETECTO	HG	95031641	30			"	"			N	5.00	
5.	DETECTO	HG	95031642	30			"	"			N	5.00	
6.	DETECTO	HG	95031643	30			"	"			N	5.00	
7.	DETECTO	HG	95031644	30			"	"			N	5.00	
8.	HOBART	CP	171023699	30	0	OK	OK	OK	W	OK	30	A	5.00
9.	HOBART	CP	171044079	30	0	OK	W	W	W	W	30	A	5.00

NOTICE: All device inspection fees shall be paid within thirty days of the issuance of the original invoice. Any fee not paid within ninety days after the date of the original invoice will be cause for the director to deem the device as incorrect and it may be condemned and taken out of service, and may be seized by the director until all fees are paid. Section 413.225 RSMo Effective 8-28-02

MAKE CHECK PAYABLE TO:
 SCALE PROGRAM, WEIGHTS AND MEASURES. SEND TOTAL AMOUNT DUE WITH BLUE COPY

RECEIPT OF REPORT ACKNOWLEDGED <i>[Signature]</i>	INSPECTOR <i>[Signature]</i>	PAGE TOTAL 10.00 TOTAL AMOUNT DUE AT INSPECTION \$80.00
--	---------------------------------	--



MISSOURI DEPARTMENT OF AGRICULTURE
 DIVISION OF WEIGHTS AND MEASURES SCALE PROGRAM
 P.O. BOX 830, JEFFERSON CITY, MISSOURI 65102 (573) 751-5629
SCALE INSPECTION REPORT/FEE INVOICE

MAY 02 2007

COUNTY GREENE	PROP. CODE 04	PAGE 02 OF 03
DATE 4-24-07	INVOICE NUMBER 203533	

FIRM NAME AND STREET ADDRESS 077-0095 PRICECUTTER #18 1901 E DIVISION SPRINGFIELD TELEPHONE NUMBER (417)866-5502	BILLING ADDRESS IF DIFFERENT PRICECUTTER #18 1901 E DIVISION SPRINGFIELD, MO 65803 TELEPHONE NUMBER
--	---

NAME	TYPE	SERIAL NUMBER	CAPACITY	ZERO AS FOUND	0 TO 1 LB.	1% TEST LOAD	10 TEST LOAD	SHIPT	75% TEST LOAD	MAXIMUM TEST LOAD	ACTION CODE	FEE
1. HOBART	CP	171044442	30	0	OK	OK	-1d	OK	-1d	30 ^{-2d}	A	5.00
2. HOBART	CP	171055062	30	0	OK	OK	OK	1d	-1d	30 ^{-1d}	A	5.00
3. HOBART	CP	171061762	30	0	OK	OK	OK	OK	+1d	30 ^{+1d}	A	5.00
4. HOBART	HG	1015716	30			NOT Sealed					N	5.00
5. HOBART	PK	171029532	30			Dabte					D	5.00
6. HOBART	PK	311289310	30	0	OK	OK	-1d	OK	-1d	30 ^{-1d}	A	5.00
7. NCR	CP	5033832158	30	0	OK	OK	-1d	1d	-1d	30 ^{-1d}	A	5.00
8. NCR	CP	5034706375	30	0	OK	OK	OK	1d	OK	30 ^{ad}	A	5.00
9. NCR	CP	5034732305	30	0	OK	OK	OK	1d	OK	30 ^{ad}	A	5.00

NOTICE: All device inspection fees shall be paid within thirty days of the issuance of the original invoice. Any fee not paid within ninety days after the date of the original invoice will be cause for the director to deem the device as incorrect and it may be condemned and taken out of service, and may be seized by the director until all fees are paid. Section 413.225 RSMo Effective 8/29/02

MAKE CHECK PAYABLE TO: SCALE PROGRAM, WEIGHTS AND MEASURES. SEND TOTAL AMOUNT DUE WITH BLUE COPY

PAGE TOTAL
35.00
TOTAL AMOUNT DUE AT INSPECTION

RECEIPT OF REPORT ACKNOWLEDGED	INSPECTOR <i>Tim Rose</i>	See page 1
--------------------------------	------------------------------	------------



MISSOURI DEPARTMENT OF AGRICULTURE
 DIVISION OF WEIGHTS AND MEASURES SCALE PROGRAM
 P.O. BOX 830, JEFFERSON CITY, MISSOURI 65102-0830 781-5639
 SCALE INSPECTION REPORT/FEE INVOICE

MAY 08 2007

COUNTY GREENE	INSP CODE 04	PAGE 03 OF 03
DATE 4-24-07	INVOICE NUMBER 203533	

FIRM NAME AND STREET ADDRESS 077-0095 PRICECUTTER #18 1901 E DIVISION SPRINGFIELD TELEPHONE NUMBER (417)866-5502	BILLING ADDRESS IF DIFFERENT PRICECUTTER #18 1901 E DIVISION SPRINGFIELD, MO 65803 TELEPHONE NUMBER
---	---

	NAME	TYPE	SERIAL NUMBER	CAPACITY	ZERO AS FOUND	0 TO 1 LB.	1/4 TEST LOAD	1/2 TEST LOAD	SHIFT	3/4 TEST LOAD	MAXIMUM TEST LOAD	ACTION CODE	FEE
1.	NCR	CP	5034732327	30	0	OK	OK	OK	OK	OK	30 ^{ad}	A	5.00
2.	NCR	CP	5034732339	30	0	OK	OK	OK	OK	OK	30 ^{tid}	A	5.00
3.	NCR	CP	5034732353	30	0	+1d	+2d	+12d	1d	STOP TEST		R	5.00
4.	NCR	CP	5034732363	30	0	OK	OK	-1d	1d	-1d	30 ^{-1d}	A	5.00
5.	NCR	CP	5034732369	30	0	OK	OK	+1d	OK	+1d	30 ^{+1d}	A	5.00
6.	NCR	CP	5034732371	30	0	OK	-1d	-1d	OK	-2d	30 ^{-2d}	A	5.00
7.	Hobart	PK	171027520	30	0	OK	OK	OK	1d	-1d	30 ^{-1d}	A	5.00
8.													
9.													

NOTICE: All device inspection fees shall be paid within thirty days of the issuance of the original invoice. Any fee not paid within ninety days after the date of the original invoice will be cause for the director to deem the device as incorrect and it may be condemned and taken out of service, and may be seized by the director until all fees are paid. Section 413.225 RSMo Effective 8-29-02.	MAKE CHECK PAYABLE TO: SCALE PROGRAM WEIGHTS AND MEASURES. SEND TOTAL AMOUNT DUE WITH BLUE COPY.	PAGE TOTAL 35.00 TOTAL AMOUNT DUE AT INSPECTION <i>See page 1</i>
RECEIPT OF REPORT ACKNOWLEDGED	INSPECTOR <i>Tim Rosen</i>	